

Top Entry Collector

1. Connect mounting bracket to boom using mounting hardware provided. There are two holes provided to attach the collector mounting bracket in place.
2. Attach the collector to the top side of the collector mounting bracket.
3. Connect the power supply from an overhead source into the connector.
4. Rotate the crane to its full degree of rotation in both directions to ensure wires are free from obstruction and no binding occurs.
5. Check all fittings for leaks and assure connections are securely fastened.

Refer to drawing AJ360 - TEC for additional references.