

Free Standing Work Station Jib Crane Top Entry Collector Installation Instructions

Top Entry Collector for WSJ360

- 1. Connect mounting bracket to boom using U-bolt and mounting hardware provided.
- 2. Attach the top entry collector to the mounting bracket using hardware provided.
- 3. Remove cover from collector.
- 4. Connect the lifting device to the collector through the outlet in the side of the collector.
- 5. Replace cover of collector housing.
- 6. Connect power source to the top inlet of the collector.

Refer to drawing WSJ360.TEC for additional references.