

## Free Standing Jib Crane Top Entry Collector Installation Instructions

## Top Entry Collector for FS300, FS350 & FS350S

- 1. Drill holes in boom (if required), or attach mounting plate to boom (if required), refer to General Arrangement drawing for mounting assembly.
- 2. Attach the top entry collector to the mounting bracket using hardware provided.
- 3. Remove cover of collector.
- 4. Connect the lifting device to the collector through the outlet in the side of the collector.
- 5. Replace cover of collector housing.
- 6. Connect power source to the top inlet of the collector.

Refer to drawing TECA for additional references.

www.gorbel.com Phone: (585) 924-6262 Toll Free Phone: (800) 821-0086 © 2012 Gorbel Inc. All Rights Reserved